



C1 = 0,001 μ F ;
 C2 = 0,1 μ F ;
 C3 = 5,000 μ F ;
 C4 = 0,0005 μ F ;
 C5 = 0,01 μ F ;
 C6 = 3 μ F ;
 C7 = 4 μ F ;
 R1 = 400 ohms ;

R2 = 50.000 ohms ;
 R3 = 250.000 ohms ;
 R4 = 25.000 ohms ;
 R5 = 1.000.000 ohms ;
 R6 = 500.000 ohms ;
 R7 = 600 ohms ;
 R8 = 180 ohms ;
 R9 = 50.000 ohms ;
 R10 = 100.000 ohms.